INSTALLATION INSTRUCTIONS for EG and DC SERIES FOLDING GATES (NON-PIVOT)

TOP TRACK MOUNTING: PLAN A CEILING PLAN B FACE

- 2. -IDENTIFY MOUNTING LOCATION. ATTACH MOUNTING BRACKET FOR THE TOP TRACK ON FACE OF WALL, ASSURING THE TOP OF THE TRACK IS AT THE
- ω 4 ATTACH THE TOP TRACK TO THE MOUNTING BRACKETS.
- AT 1" FROM EACH END OF THE TOP TRACK DROP A PLUMB LOCATING MOUNTING POSITION FOR THE REAR BAR POST BOB FROM THE CENTER OF THE TRACK TO THE GROUND MARK POSITION.
- Ş DRILL 5/8" HOLE IN FLOOR ABOUT 2" DEEP AT MARKED POSITION. THIS HOLE WILL ACCEPT THE LOWER MOUNTING PIN
- 6. PLACE RACKED (CLOSED) GATE WITH ATTACHED END BAR IN VERTICAL POSITION WITH LOWER MOUNTING PIN INTO
- ATTACH SADDLE BRACKET ON THE TOP OF THE REAR BAR/ LOCKING POST TO THE TOP TRACK.
- 9 00 AND PROCEED TO NEXT STEP. IF GATE IS BI-PARTING, REPEAT STEPS 1 THROUGH 8 ABOVE
- AFTER MOUNTING BOTH SEGMENTS OF THE GATE, PULL THE MARK LOCATION ON FLOOR. ONE OF THE LEAD BARS. DROP CANE BOLT TO FLOOR AND CONNECTED WITH EACH OTHER. A CANE BOLT IS LOCATED ON TWO GATES TOGETHER SO THAT THE LEADING BARS ARE
- 10. BEFORE DRILLING HOLE CHECK TO INSURE BOTH GATE HALVES OR SECTIONS HAVE APPROXIMATELY THE SAME SPACING.
- 11. DRILL 7/8" HOLE TO ACCOMMODATE 3/4" CANE BOLT DEEP ENOUGH TO ALIGN PADLOCK HASPS PLUS AN ADDITIONAL INCH FOR ACCUMULATION OF DUST AND/ OR DEBRIS.
- 12. CLEAN UP AREA AND USE TOUCH UP PAINT AS NECESSARY ON GATE BODY, FASTENERS ETC







